

E R R O R M E M O R Y R E P O R T

Date: 09/05/11 14:34:47
ECU: D\_STVR2
JobStatus: ---

- API-Job FsLesen: job status error
- API-Job FsLesen: job status error

Variant: CVM IV >>>>>>>> No error found <<<<<<<<<<
Variant: LSZ 2 1 Error in error memory
Error registration 1 : 0x0022: VHAC, front load sensor short-circuit to ground <<<<!!!
Error accurances: 2
Error not present
Error code: 22 02

Ecu : D 0066 IFH-0009: NO RESPONSE FROM CONTROLUNIT

Variant: RLS\_DS2 >>>>>>>> No error found <<<<<<<<<<
Variant: PDCACT >>>>>>>> No error found <<<<<<<<<<
Variant: EWS3 >>>>>>>> No error found <<<<<<<<<<
Variant: LWS5 1B >>>>>>>> No error found <<<<<<<<<<
Variant: ZKE5 >>>>>>>> No error found <<<<<<<<<<
Variant: SZM46 >>>>>>>> No error found <<<<<<<<<<
Variant: KOMBI85 >>>>>>>> No error found <<<<<<<<<<
Variant: IHKA85 >>>>>>>> No error found <<<<<<<<<<
Variant: RADIO >>>>>>>> No error found <<<<<<<<<<
Variant: TOPDSP >>>>>>>> No error found <<<<<<<<<<
Variant: ULF >>>>>>>> No error found <<<<<<<<<<

Ecu : D\_00F0 SYS-0012: IDENTIFICATION ERROR

Variant: VM5IBUS >>>>>>>> No error found <<<<<<<<<<
Variant: NAVMK4\_2 >>>>>>>> No error found <<<<<<<<<<

Ecu : D 0048 IFH-0009: NO RESPONSE FROM CONTROLUNIT

Variant: NAVMK4 2 >>>>>>>> No error found <<<<<<<<<<

Ecu : D 00BB SYS-0012: IDENTIFICATION ERROR

Variant: SM46 4 >>>>>>>> No error found <<<<<<<<<<

Ecu : D 00DA SYS-0012: IDENTIFICATION ERROR

#####
This content will stored temporary temporär in ..\inpa\sgdat\na\_fs.tmp
#####